



SERVICE LETTER

SUBJECT:

Water drain hole

AFFECTED PRODUCTS:

Fuselage

Water leaking issues that's running from the tail to the inside belly

AFFECTED SERIAL NUMBERS:

#2022001

COMPLIANCE:

MANDATORY

INSTRUCTIONS:



Maximum hole diameter 8mm (0,315 in),

Drill a hole according to the photo, 550 mm (21,65 inch) from the end of the fuselage and in the axis of the fuselage. Drill it in two steps. First a hole of diameter 4mm (0,157 inch) then 8mm (0,315 inch) max!!!!

